
1610.3.

No. NHVI-50 (3)/83

Dated the 12th April 1983

To

The Chief Engineers of all State P.W.Ds and Union Territories dealing with NHs and other Centrally Financed Roads

Sub. Lay-out for construction of bridges on National Highways and other Centrally sponsored road

It has been observed in some cases that the abutments are wrongly located at site. In order to avoid such a situation, it is requested that the lay-out at site before the start of construction of bridges may please be fixed by a responsible officer of the State P.W D not below the rank of an Executive Engineer.